Author: Edd Kray/SiteReps/rffo at RFFO

Date: 10/28/97 9:07 AM

Priority: Normal

TO: Mark Hickman at Hotel17

CC: chris.gilbreath@state.co.us at RFFO CC: steve.tarlton@state.co.us at RFFO CC: aguilar.mark@epamail.epa.gov at RFFO

Subject: 779 DOP

----- Message Contents -----

Mark,

please see that Kathy and Mike Korenko get a copy of this. They don't seem to be on the mail system.

Review of the most recent DOP elicits the following comments for resolution. Lets discuss these Wednesday.

- 1. Review of my past comments shows a few to be, as yet,unresolved. I'll bring my copies of past comments.
- 2.(p 41) Is the last bullet under the glove-box section in the right place? Isn't this talking about structure decon vs GB's?

The old DPP and DOP and RFCA indicated that the operator and CDPHE would meet to discuss decontamination approaches and options before establishing the final decon approach and levels for structural components prior to building demolition. We need to add a paragraph describing this process.

- 3. (p 44) DOE surveys will not meet the need for independent verification. Delete this.
- 4. (p 50) The table of release criteria has been eliminated. It must be in the DOP.
- 5. (p 63) Let's not forget to mention rad hazards in the box for HVAC. Hozard of whilation.
- (p 66) We stll differ on the statement that " if costs to demonstrate that an item is not contaminated exceeds the costs for waste disposal, the item will be disposed of as waste". Lets work out a compromise position. d
- 7. We seem to have lost any committment for the state to be involved in the environmental readiness assessment. process need to put this back in somewhere.
- 8. I hear that DOE is calling for removal of the management structure materials. This may keep the document from being approvable. Ask them to rethink this.

I note, from RFCA, section 104, that we, the state, needs prepare a "draft permit decision" to go along with the DOP when it is released for public comment. Let's get these issues resolved so that we can start on this.

Best Available Copy

DMIN RECCRD B779-A-000189

